

Consideration of Comments on Initial Ballot of Urgent Action Change to Coordinate Interchange Timing Tables

Voter	Entity	Comment
Allen Klassen	Westar Energy	WECC only
<p>Response: The changes made to the timing table do apply solely to WECC.</p>		
Terry Bilke	Midwest ISO, Inc.	<p>While we do not have an issue with the proposed change, this appears to be a misuse of the Urgent Action process. The process should be used when there is urgency to preserve reliability, not for expediency of the standards process. This is particularly important given the safeguards (such as sunset) have been removed from the Urgent Action process.</p>
<p>Response: The requestor did provide a reliability-related justification for this Urgent Action – the error in the existing timing table does not provide the reliability entities with sufficient time to conduct a reliability analysis of the Arranged Interchange.</p>		
Christopher Lawrence de Graffenried	New York Power Authority	CP-9 agrees with this SAR
<p>Response: The requestor thanks you for your support.</p>		